

SERVICE BULLETIN

from: TRIO-KENWOOD COMMUNICATIONS, INC.

56

SUBJECT:

TS-180S DFC


DATE 9/10/79

For complaints of either induced power supply hum, or intermittent frequency stability while using the DFC, perform the following changes to the VCO unit X50-1550-00:

- *1. Install a 330K ohm resistor between Q11 G1 & the 8V line. Connect from L7 at C12 to Q11 G1, at R35.
- *2. Replace L12 68uH with new part L40-6831-21.
- *3. Replace L13 150uH with new part L40-1541-27.
- *4. Install magnetic shield as illustrated. Use the two existing screws, plus double faced tape to prevent vibration.
- * New Part

No adustments are necessary.

Note: On page 37 of the Service Manual, the VCO Board view shows reversed callouts for Qll & Ql5. D & S, and Gl & G2 are transposed.



This bulletin supercedes previous DFC bulletins of 7/10/79 and 7/13/79.

Please notate your Service Manual.

JEB/yn

TRIO-KENWOOD COMMUNICATIONS, INC.

1111 WEST WALNUT STREET - COMPTON, CALIFORNIA 90220 MAILING: P.O. BOX 7065 - COMPTON, CALIFORNIA 90224