



SERVICE BULLETIN

from: TRIO-KENWOOD COMMUNICATIONS, INC.

TS-660

#856



SUBJECT: TS-660 Microprocessor Latchup

DATE 1/25/82

Microprocessor latchup may occur if the power switch is cycled several times in quick succession, if the supply is turned off while the power switch remains on, or if the power supply is turned on with the transceiver already on. Symptom will be no display, erroneous display, or locked display. Change two components on the Control unit to prevent further trouble.

On the Control unit X53-1220-00:

1. Replace R23 680 Ω with a 470 Ω resistor (RD14CB2E471J).
2. Remove and delete C4 47 μ F
3. Add a 22 μ F 16V electrolytic (CE04W1C220M) on the foil side of the board between D24, R23 (positive) and ground (negative).



- Notes:
1. This change applies to units before serial number 209xxxx.
 2. Installation time for this procedure is 1/2 hour or less.

JEB/sh

TRIO-KENWOOD
COMMUNICATIONS, INC.

1111 WEST WALNUT STREET - COMPTON, CALIFORNIA 90220
MAILING: P.O. BOX 7065 - COMPTON, CALIFORNIA 90224