

SERVICE BULLETIN Amateur Radio Group

SUBJECT TM-732A 2Meter Transmit Interference on 70 CM DATE

May 20, 1992

Reports of 70 cm receiver interference might occur when transmission is attempted on This is caused by a harmonic relationship that occurs between some 2 two meters. meter frequencies and the IF image frequency. The resulting signal enters IC201 (FM HIC) on the 8R line of the 430 MHz TX/RX Unit.

Addition of a chip bead and bypass capacitor on the 8R line will correct this tendency.

Parts Required:


470 pF chip capacitor

CK73FB1H471K

Chip bead

L92-0131-05

Note: Don't confuse the chip capacitor with the chip bead. They have the same shape. The chip bead is black and the chip capacitor is brown so it should be a simple matter to identify the correct part.



430 MHz TX/RX Unit (X57-4000-XX) Foil Side View

Time required for this modification is 30 minutes.

Copyright Kenwood U.S.A. 5/20/92 (CLM)

Communications & Test Equipment Division

KENWOOD U.S.A. CORPORATION Communications & Test Equipment Division 2201 E. Dominguez Street Long Beach, California 90810 Phone: (310) 639-7140 FAX: (310) 631-3913