



SERVICE BULLETIN

from: TRIO-KENWOOD COMMUNICATIONS, INC.

TS-930 & other models #863

SUBJECT: Incorrect AC line voltage setting

DATE 10-22-82

It has been found that a few TS-930S (and other) transceivers have been shipped in the 220V or 240V Line position. If you should encounter an initial transceiver failure, please check for correct line voltage selector setting. The voltage selector is located on the bottom case at the rear of the unit.

JEB/sh

TRIO-KENWOOD
COMMUNICATIONS, INC.

1111 WEST WALNUT STREET - COMPTON, CALIFORNIA 90220
MAILING: P.O. BOX 7065 - COMPTON, CALIFORNIA 90224