

KENWOOD

ASB-1038

Service Bulletin

Amateur Radio Division

Subject: TH-78A Microprocessor Change

Date: February 10, 1994

Symptom:

Due to a recent rule change by the FCC it is no longer possible to supply transceivers, or provide replacement microprocessors that would allow a transceiver to receive in the 800 MHz band.

Corrective Action:

The microprocessor program of IC5 has been modified to prevent 800 MHz band reception. Production has been changed beginning with serial number lot 510XXXX. Units produced after this point will not be capable of 800 MHz reception.

Parts Required:

Qty	Description	Old Kenwood Part No.	New Kenwood Part No.
1	Microprocessor	75517GF-170-3B9	75517GF-257-3B9

Procedure:

When ordering a replacement microprocessor you will be supplied with the new version. Please make sure your customer understands the limitations of this new microprocessor.