



SERVICE BULLETIN

from: TRIO-KENWOOD COMMUNICATIONS, INC.

NO. 3

SUBJECT: QR-666 VFO STABILITY

DATE 10-01-75

Trio-Kenwood is extremely proud of the reliability of our communications gear. Quality control is performed at our Tokyo factory as well as Gardena, California facility.

We have found that a small percentage of the QR-666 SWL receivers may have a slight case of instability if carelessly handled in shipping.

Here is a simple cure we've found to eliminate the symptoms:

Check all screws which hold the RF circuit board (the one with band switch attached). Check top and bottom screws (holding spacers to chassis).

You'll probably never have this problem, but.....

