

## SERVICE BULLETIN Amateur Radio Division


**SUBJECT**

DSP-100 6-Pin Cable


**DATE**

January 26, 1992

Difficulty might be encountered when connecting early versions of the DSP-100 to a TS-450S or TS-690S transceiver. No problems have been encountered with the TS-850S and the DSP-100. The length of the connector on the radio side of the cable might not be sufficient to ensure proper connection when connected to the TS-450 series. The connector has been changed on later versions of the DSP-100 to provide proper contact with these transceivers. The accompanying illustration shows the basic difference between the two cable assemblies. No problem should be encountered when using the new cable with any DSP-100 capable transceiver.



E30-3047-05  
Old Part Number



E30-3047-15  
New Part Number

(C) January 26, 1992 Kenwood U.S.A. Corp.

Communications & Test Equipment Group

KENWOOD U.S.A. CORPORATION  
Communications & Test Equipment Group  
2201 E. Dominguez Street  
Long Beach, California 90810  
Phone: (310) 639-7140  
FAX: (310) 631-3913