

SERVICE BULLETIN

AMATEUR RADIO


SUBJECT

TS-430S NOTCH CONTROL

DATE

11-07-83

Notch/Squelch control (VR5) may be replaced with part number R24-9403-15, to allow greater flexibility in adjustment. As can be seen from the chart below, the curve is smoother on the high frequency side (1 kHz to 2.7 kHz), making tuning easier. VR5 is located on Switch unit (X41-1470-00).



Note: This is an optional change and may not be performed in warranty.

CLM