

KENWOOD

SB-980


SERVICE BULLETIN AMATEUR RADIO

SUBJECT TM-941A BPF ALIGNMENT TOOL	DATE 12/06/90
---------------------------------------	------------------

The 144 MHz receiver Band Pass Filter adjustments on the TM-941A require a 1.5mm square tip alignment tool.

G.C. Electronics carries a tool in their catalog that can be modified to fit the BPF adjustments. The tool is catalog number 9440.

The square tip side of this tool is 1.6mm square. Two sides of the tip need to be ground down so that the tip becomes 1.5mm square.



Copyright (C) 120690EWP for Kenwood U.S.A. Corporation.